

## Additional Emergency Exit for Flight Tests

Paulo Quattrocchi EMBRAER Flight Test FTSW, Seattle, 05.02.2012

#### Summary

- Introduction;
- Requirements for acft. exits;
- Emergency Exit: 80s and 90s;
- Aditional Emergency Exit: 21th century;
- New products
- Lessons Learned
- Q&A

This presentation covers historical events, the last 20 years learning results on additional emergency exits for EMBRAER flight test prototypes, submitted to a civil certification process (ANAC, FAA, EASA), and the latest features added to the Legacy 500 (001 and 002 prototypes), with its test results.

#### FAR for Exits

#### • 25.561

(a) acft. must be designed to protect each occupant.(b) designed to give chance of escaping in a minor crash landing;

(d) Seats and items of mass must not deform, that would impede evacuation of occupants.

#### • 25.562

## Restraint sys: proper use, performance, Head Impact Criteria...

#### FAR for Exits

• 25.807

Type of exits (I, II, III, IV, A, B, C...) size, ground clearance....

• 29.783 Doors: latches, locks, access, strenght....

• 29.809 Emergency Exits: works, functions and slides

#### **Identified High Risk Situations**

- Ground Egress:
  - Vmcg, Vmu, Brake Efficiency, Max.Kinectic
    Energy, Quick Tourn Around, Landing Perf.,
    Steep Approach, Take Off Perf., Water ingestion;
- Stabilized Flight Bail-out:
  Deep Stall, Flat spin;

 Uncontroled Flight Bail-out: - Structural failure.

#### FAR for Exits

• FAR 21.35 (d) provision is made for the flight test crew for emergency egress and the use of parachutes.

 Passenger doors, emergency doors or windows commonly supplied for passenger usage are not meant to be used <u>in motion</u>, nor on situations encountered on <u>envelope opening</u> of the compliance demonstration process.

 Regarding the above listed requirements our team asked for <u>additional</u> safety features to be installed on the flight test articles


### "The additional exit for flight test"

#### EMBRAER history: EMB-110 – Bandeirante

Early 70s • FAR 23 req. cert.; 18 pax, 13000 lb mtow; Emg. Window & pax door FORCA AÉREA BRASILEIRA No additional exit features !

8

#### EMBRAER history: EMB-121 – Xingu



🗲 EMBRAER


9

#### EMBRAER history: EMB-120 – Brasilia

- Late 80s;
- 30 pax, 25300 lb mtow;
- FAR 25 req. cert.;
- One pax door;
- 2 emg. windows, one right emg. door;

# Bungee actuated emergency windowBungee actuated seat rail

#### EMB-120: Bungee actuated seat rail




#### EMBRAER history: CBA-123 – Vector

FE ANILIA

- Early 90s;
- 19 pax, 17000 lb mtow;
- FAR 25 req. cert.;
- One pax door;
- 2 emg. windows, 1 pax. door;
- Pusher fans

Ventral Exit

#### **CBA-124: Ventral Exit**



- The exit was through the right ldg enclosure;
- The escape sequency was: lower ldg, depressurize acft., run to the back, jump through hole


#### **EMBRAER** history: ERJ-145

# **Explosive** windows • 50 pax, 48500 lb mtow; • FAR 25 req. cert.; • Pax, Service, Cargo doors & 2 emg. windows • 1st jet acft !

🗲 EMBRAER

14 This information is the property of Embraer and cannot be used or reproduced without written consent.

#### **ERJ-145: Bailout Ballistic**



🗲 EMBRAER

#### **ERJ-145: Explosive windows**

• The exit was through the cockpit windows and a blown up hole on the right side of the fuselage.

• The escape sequency was:

Push trigger, jump out.



#### Hollow Charge


V or U chaped explosive chord, that focus the explosive energy into a single narrow point, INPORTED az INPORTED az INPORTED az INPORTED az INPORTED az INPORTED AZ producing a predictive and controled cut.

Munroe effect or Neumann effect

Conical Line

- EMBRAEF

#### **ERJ-145: Explosive windows**





2nd try

🗲 EMBRAER

#### ERJ-145: Explosive windows





#### EMBRAER flightline today: E170/ E175



20 This information is the property of Embraer and cannot be used or reproduced without written consent.

🗲 EMBRAER

#### Additional exit (BAC-111 2nd prototype)




#### E170, E190: Escape Hatch



"Potty"





🗲 EMBRAER

#### E170, E190: Escape Hatch



🗲 EMBRAER

#### E-170: "Potty" hole



depressurize acft., run all the way to the back, blow the door, jump through hole Escape Hatch

#### E-175, E-195



# "Fast" opening door for pressurized situations.


#### Phenom 100 / 300



#### Phenom 300: Extraction Markings



#### Phenom 100 / 300: extraction markings



#### Upcoming EMBRAER Flightline

- 14 pob, 41800lb mtow
- FAR 25 req. cert.
- Pax door, 1 emg. Window
- M 0.83
- Full FBW

### Legacy 500 / 450

ZEY

#### **Identified High Risk Test Situations**


- Ground Egress:
  - Vmcg, Vmu, Brake Efficiency, Max.Kinectic
    Energy, Quick Tourn Around, Landing Perf.,
    Steep Approach, Take Off Perf., Water ingestion;
- Stabilized Flight Bail-out:

-Deep Stall, Flat spin; Flight controls malfunction,


• Uncontroled Flight Bail-out:

- Structural failure; Flight Controls Departure, Flight Controls Inop.

#### Legacy 500: Additional Exit Options




#### Legacy 500: Additional Exit Options



This information is the property of Embraer and cannot be used or reproduced without written consent.


#### Legacy 500: Bailout Ballistic



#### Legacy 500: Additional Exit Options


position	description	ground egress	stabilized flight bail out				project and implementation
			high speed	flat spin	high alfa	high load	
1	rh lateral 4h	may be obstructed in ground	possible wing hit	possible engine hit	possible engine hit	clear bail out	feasible
2	rh lateral 3h	not obstructed in ground	clear bail out	possible tail hit	possible tail hit	clear bail out	feasible: more explosives than pos 1
3	rh lateral 5h	obstructed on ground	possible wing hit	possible engine hit	possible engine hit	clear bail out	feasible: more explosives than pos 2; cable and system changes
4	front floor	obstructed in ground	possible belly hit	possible belly hit	possible belly hit	clear bail out	feasible: more explosives than pos 3; cable and system changes
5	cabin door (lh)	obstructed on ground	clear bail out	possible tail hit	possible tail hit	clear bail out	Need 10 explosive pins. Difficult operation, installation and removal.
6	rh lateral emerg. window	not obstructed on ground	clear bail out	possible engine hit	possible engine hit	possible wing hit	must include long opening handle
7	cockpit side window	not obstructed on ground	not enough space to bail out with parachute				Must explode wider area than available

#### Legacy 500: Additional Exit Options




🗲 EMBRAER


#### Legacy 500: Emerg. Window Handle



## Legacy 500 Additional Emergency Exit




#### Legacy 500: Explosive Trigger Positions



38 This information is the property of Embraer and cannot be used or reproduced without written consent.

### Legacy 500: Explosive frame



#### Explosive charge test #1 - before



#### Explosive charge test #1

# Explosive charge test #1 - after



#### Explosive charge test #2 - before



43 This information is the propert

#### Explosive charge test #2

#### Explosive charge test #2 - after



🗲 EMBRAER

- Gvmt. (safety) requirements are not enough for envelope opening flight tests ;
- Extra safety devices may require structural changes;
- Extra safety devices may not interfere with tests and its conformity;
- Development Schedule and tight budget may easily push a Corporate No-Go decision;
- <u>Almost</u> the same recipe may turn out in <u>almost</u> a different cake;
- Do not produce a safety device that results in more danger than if you did not have it !

#### Questions ?



Paulo Quattrocchi Email: <u>quatroque@embraer.com.br</u> Phone: + 55 12 3927-3171

# Thank You !

FOR THE JOURNEY

