

WEBVTT

1

00:00:05.335 --> 00:00:05.805

Thank you.

2

00:00:09.275 --> 00:00:11.645

Good morning. So I've got for you today a pretty, uh,

3

00:00:11.675 --> 00:00:15.165

classic example of a fundamental meeting between fly

4

00:00:15.165 --> 00:00:16.725

by wire flight controls and physics.

5

00:00:17.305 --> 00:00:19.125

Uh, before I start, I wanna thank, uh,

6

00:00:19.205 --> 00:00:21.245

Colonel Hank Vanderberg at PMA 2 61

7

00:00:21.265 --> 00:00:22.685

for authorizing this presentation

8

00:00:22.685 --> 00:00:24.365

and Sikorsky for allowing me to speak.

9

00:00:24.515 --> 00:00:26.805

They've let me be pretty frank with my comments today,

10

00:00:26.805 --> 00:00:28.165

so I think that's probably a good thing in terms

11

00:00:28.165 --> 00:00:29.205

of flight test lessons learned.

12

00:00:31.265 --> 00:00:32.925

So today I'll take you through the, uh, background

13

00:00:32.925 --> 00:00:33.925

of 53 K initially.

14  
00:00:34.345 --> 00:00:36.565  
Uh, talk about the ground test that we did leading up

15  
00:00:36.565 --> 00:00:38.765  
to first, uh, initial ground runs

16  
00:00:38.765 --> 00:00:40.485  
with blades on and then to first flight.

17  
00:00:40.945 --> 00:00:42.165  
Uh, pretty major discovery

18  
00:00:42.165 --> 00:00:45.245  
that we found on the ground test vehicle, uh,

19  
00:00:45.395 --> 00:00:47.885  
what the design error was, how we missed it in flight test,

20  
00:00:47.905 --> 00:00:49.485  
and that's gonna be the focus of the brief.

21  
00:00:49.625 --> 00:00:51.685  
I'm not a design engineer on this, on this aircraft,

22  
00:00:51.685 --> 00:00:52.685  
but I was a tester involved.

23  
00:00:52.685 --> 00:00:54.005  
So I'm gonna talk mostly about test

24  
00:00:55.305 --> 00:00:56.365  
and we'll talk about recovery

25  
00:00:56.745 --> 00:00:58.245  
and our flight test progress since then.

26  
00:00:58.245 --> 00:00:59.445  
So you'll see this has a happy ending.

27  
00:00:59.445 --> 00:01:00.445

Like some of the other briefs.

28

00:01:03.535 --> 00:01:07.485

53 K was specified as a replacement for the CH 53 echo.

29

00:01:07.945 --> 00:01:09.445

Its mission is mostly heavy cargo,

30

00:01:09.465 --> 00:01:10.685

but also for troop transport.

31

00:01:11.105 --> 00:01:14.525

Uh, the idea is to deliver a heavy payload at 110 nautical

32

00:01:14.525 --> 00:01:16.405

miles, double the 47 F

33

00:01:16.405 --> 00:01:18.805

and about triple what the V 22 can do at that range.

34

00:01:19.385 --> 00:01:21.365

You hear a lot of people say that it has tripled the

35

00:01:21.525 --> 00:01:23.565

external load lift capability of the 53 echo.

36

00:01:23.565 --> 00:01:26.485

That's not really right. They can lift about the same thing,

37

00:01:26.505 --> 00:01:28.325

but again, it's a range, uh, factor.

38

00:01:28.345 --> 00:01:30.365

So we have much more range with, with the heavy load.

39

00:01:31.025 --> 00:01:33.005

So for this mission that we, that's depicted here,

40

00:01:33.005 --> 00:01:35.725

it's a 27,000 pound external load lift from

41  
00:01:35.765 --> 00:01:36.805  
a, uh, from a ship.

42  
00:01:37.345 --> 00:01:39.085  
And then, uh, the idea is fly it at

43  
00:01:39.085 --> 00:01:40.525  
marine high hot conditions.

44  
00:01:40.585 --> 00:01:41.805  
So 91.5 degrees

45  
00:01:41.805 --> 00:01:45.845  
and 3000 feet pressure, 110 nautical miles, drop it off

46  
00:01:45.945 --> 00:01:47.525  
and then come home, uh, from

47  
00:01:47.525 --> 00:01:48.685  
that, uh, external load mission.

48  
00:01:49.105 --> 00:01:50.285  
So again, quite a bit more

49  
00:01:50.285 --> 00:01:51.765  
capability than what the Echo has.

50  
00:01:52.385 --> 00:01:55.045  
And, um, you'll see how we can achieve that in terms of our,

51  
00:01:55.065 --> 00:01:56.205  
uh, uh, performance.

52  
00:01:57.465 --> 00:02:00.005  
So 88,000 pounds is our max hover gross weight.

53  
00:02:00.005 --> 00:02:01.125  
That's with an external load,

54  
00:02:01.385 --> 00:02:04.245

and that external load can be as heavy as 36,000 pounds.

55

00:02:05.025 --> 00:02:06.725

On the, on the right there is a picture from our

56

00:02:06.725 --> 00:02:08.005

first external loads flight test.

57

00:02:08.425 --> 00:02:09.685

So the objective of that test was

58

00:02:09.685 --> 00:02:11.245

to pick up a 12,000 pound load

59

00:02:11.245 --> 00:02:13.605

and, uh, demonstrate our emergency jettison functionality

60

00:02:13.915 --> 00:02:15.685

that set us off into external loads.

61

00:02:15.805 --> 00:02:17.485

Envelope expansion on the K, um,

62

00:02:17.485 --> 00:02:19.725

having flown just about six months ago for the first time,

63

00:02:20.555 --> 00:02:21.685

with all the power you need

64

00:02:21.685 --> 00:02:24.085

to carry a 36,000 pound external load, you happen

65

00:02:24.085 --> 00:02:25.045

to have a lot of excess power

66

00:02:25.045 --> 00:02:26.205

when you don't have the external.

67

00:02:26.225 --> 00:02:28.285

So 196 knots is our max dive speed.

68  
00:02:28.905 --> 00:02:32.085  
Um, pretty fast for a helicopter, we can do about one 70 vh.

69  
00:02:32.545 --> 00:02:34.885  
So, uh, again, a pretty, pretty good capability.

70  
00:02:34.885 --> 00:02:38.085  
In terms of performance, we talk about 53 KA lot

71  
00:02:38.085 --> 00:02:39.725  
as an upgrade to the 53 echo,

72  
00:02:39.945 --> 00:02:42.165  
but in reality, this is an entirely new aircraft.

73  
00:02:42.505 --> 00:02:45.085  
The only component that is common between the 53 echo

74  
00:02:45.085 --> 00:02:47.405  
and 53 K is the refueling probe.

75  
00:02:47.785 --> 00:02:50.765  
So, uh, entirely new composite fuselage, uh,

76  
00:02:50.785 --> 00:02:52.165  
new engines, new rotor systems.

77  
00:02:52.185 --> 00:02:54.605  
So 19,000 shaft horsepower is our, uh,

78  
00:02:54.945 --> 00:02:56.245  
is our gearbox capability.

79  
00:02:56.245 --> 00:02:57.245  
We've got a little bit more engine than

80  
00:02:57.245 --> 00:02:58.085  
that for high altitude.

81  
00:02:59.825 --> 00:03:02.285

Our flight control system is a full authority fly by wire.

82

00:03:02.305 --> 00:03:04.125

So this is the first full authority fly

83

00:03:04.125 --> 00:03:06.205

by wire rotorcraft in the Marine Corps

84

00:03:06.205 --> 00:03:08.325

and Navy inventory B 22 fly

85

00:03:08.325 --> 00:03:09.685

by wire also, but not full authority.

86

00:03:09.685 --> 00:03:10.805

So this is a little bit new to us.

87

00:03:11.245 --> 00:03:12.845

I think in terms of, uh, F 35,

88

00:03:12.845 --> 00:03:14.245

we would be considered a legacy system,

89

00:03:14.545 --> 00:03:17.805

but like the F 35 B with our seven main rotor blades

90

00:03:17.805 --> 00:03:19.685

and four tail rotor blades, I will also claim

91

00:03:19.685 --> 00:03:21.205

that we have 11 control effectors.

92

00:03:24.185 --> 00:03:26.365

We have an explicit model following control law

93

00:03:26.365 --> 00:03:29.645

architecture, uh, rigidly enforced by our feedback.

94

00:03:29.865 --> 00:03:31.925

Uh, three pilot selectable control law modes.

95  
00:03:32.225 --> 00:03:34.565  
Uh, this thing is designed for level one handling qualities

96  
00:03:34.565 --> 00:03:36.645  
with a DS 33, but it's designed for

97  
00:03:36.645 --> 00:03:38.205  
that in both good visual environments

98  
00:03:38.205 --> 00:03:39.605  
and degraded visual environments.

99  
00:03:39.605 --> 00:03:41.485  
We operate a lot in the dust, so

100  
00:03:41.585 --> 00:03:44.445  
that's driven multiple modes that are pilot selectable so

101  
00:03:44.445 --> 00:03:45.885  
that depending on the ambient conditions

102  
00:03:45.885 --> 00:03:47.965  
and the visual environment, he can get what he needs.

103  
00:03:48.825 --> 00:03:50.845  
We also a unique trim active side, uh,

104  
00:03:50.845 --> 00:03:52.245  
side stick cyclic incept.

105  
00:03:52.705 --> 00:03:54.885  
So you've seen a few aircraft with side six this week.

106  
00:03:55.225 --> 00:03:56.845  
Uh, again, this is the first one for us.

107  
00:03:56.945 --> 00:03:59.085  
Uh, you know, the, the H ones have them,

108  
00:03:59.185 --> 00:04:00.485



but, uh, for a heavy helicopter,

109

00:04:00.485 --> 00:04:01.565

it's kind of a new thing for us.

110

00:04:04.705 --> 00:04:07.205

We built up to flight test with a lot of ground test,

111

00:04:07.205 --> 00:04:08.285

and I have pictured here a couple

112

00:04:08.285 --> 00:04:09.525

of pictures of our ground test vehicle.

113

00:04:10.105 --> 00:04:12.005

Uh, this was really intended for a bunch

114

00:04:12.005 --> 00:04:13.245

of risk reduction testing.

115

00:04:13.545 --> 00:04:15.645

We started off in the bare head configuration, which is

116

00:04:15.645 --> 00:04:17.205

what I have pictured, no rotor blades installed,

117

00:04:17.625 --> 00:04:19.845

and, uh, then built up to testing with blades on

118

00:04:20.425 --> 00:04:21.925

the GTV obviously was expensive.

119

00:04:21.925 --> 00:04:24.205

It's an entire CH 53 K bolted to the ground.

120

00:04:24.345 --> 00:04:26.365

So there's a hole cut in the bottom of this aircraft

121

00:04:26.665 --> 00:04:29.085

and a very large steel pedestal that is,

122

00:04:29.085 --> 00:04:30.405

uh, attached to the main gear box.

123

00:04:30.835 --> 00:04:32.845

This allows us to pull all of the power

124

00:04:32.845 --> 00:04:34.445

that the aircraft has on the ground

125

00:04:34.465 --> 00:04:36.165

and achieve all of the hub moment that we've got.

126

00:04:36.235 --> 00:04:39.565

Also, uh, in order to fully ring out the, uh, drive, train,

127

00:04:39.665 --> 00:04:42.285

and the rotor system, one of the reasons we needed

128

00:04:42.285 --> 00:04:44.485

to do rotor system testing on this air on this, uh,

129

00:04:44.485 --> 00:04:46.045

ground vehicle is that there wasn't a,

130

00:04:46.525 --> 00:04:48.005

a whirl tower in existence

131

00:04:48.005 --> 00:04:50.085

that could take our seven main rotor blades

132

00:04:50.265 --> 00:04:52.405

and spin them together to the speeds it needed to get to.

133

00:04:52.825 --> 00:04:54.485

So we needed to build an aircraft to do it

134

00:04:54.485 --> 00:04:55.605

with our, uh, three engines.

135

00:04:56.875 --> 00:04:58.565

This also allowed us quite a bit of time

136

00:04:58.785 --> 00:05:00.845

and opportunity to conduct flight control

137

00:05:00.845 --> 00:05:01.965

system and avionics testing.

138

00:05:02.115 --> 00:05:04.085

Because this was built as a full aircraft

139

00:05:04.085 --> 00:05:06.805

and not as a propulsion system test bed, we were able

140

00:05:06.805 --> 00:05:09.165

to check out all of the avionics, do quite a bit

141

00:05:09.165 --> 00:05:11.045

of flight controls work, and actually incorporate several

142

00:05:11.045 --> 00:05:13.285

flight control software versions on the ground vehicle

143

00:05:13.615 --> 00:05:14.725

prior to going to flight tests.

144

00:05:15.795 --> 00:05:18.925

This ended up being a very, uh, useful tool for us

145

00:05:18.925 --> 00:05:20.405

and very fortunate that we had bought it in

146

00:05:20.405 --> 00:05:21.445

terms of the flight control system.

147

00:05:22.145 --> 00:05:24.525

We also had, uh, something that is a little bit, um, new,

148

00:05:24.525 --> 00:05:25.645

at least in terms of its depth.

149

00:05:25.745 --> 00:05:28.485

We have a fully integrated test team between the, uh,

150

00:05:28.645 --> 00:05:30.045

Sikorsky engineers and the government.

151

00:05:30.345 --> 00:05:32.605

So, uh, the picture here is, uh, one Sikorsky pilot

152

00:05:32.625 --> 00:05:34.565

and one marine test pilot in there for bear head.

153

00:05:34.985 --> 00:05:37.045

And, uh, our flight test engineers monitor

154

00:05:37.045 --> 00:05:38.325

identically on their stations.

155

00:05:38.325 --> 00:05:40.845

So it's a, a very, uh, close knit, uh, tight working team.

156

00:05:42.745 --> 00:05:43.965

So, like I said, it was fortunate

157

00:05:43.965 --> 00:05:45.125

that we had the ground test vehicle

158

00:05:45.385 --> 00:05:46.485

for the flight control system.

159

00:05:46.545 --> 00:05:48.645

It wasn't really a system that we expected to get a lot

160

00:05:48.645 --> 00:05:49.965

of discovery out of, but we did.

161

00:05:50.505 --> 00:05:53.485

Um, so after the very first bladed ground run in, uh,

162

00:05:53.485 --> 00:05:56.245

April a couple of years ago, the structures engineers noted

163

00:05:56.245 --> 00:05:58.485

that their tail rotor loads were higher than they expected.

164

00:05:58.985 --> 00:06:01.405

So initially, of course, we blamed this on instrumentation

165

00:06:01.715 --> 00:06:03.645

that clearly the loads must have been wrong.

166

00:06:04.105 --> 00:06:06.685

Uh, instrumentation asked us, Hey, what are the loads on

167

00:06:06.685 --> 00:06:08.085

that tiedown strut there?

168

00:06:08.385 --> 00:06:10.525

So we found that the loads on the tiedown strut agreed

169

00:06:10.525 --> 00:06:12.485

with the tail rotor, uh, measured strains.

170

00:06:12.705 --> 00:06:13.805

So obviously something was real.

171

00:06:14.425 --> 00:06:16.725

Um, we saw the high compressive loads and,

172

00:06:16.725 --> 00:06:18.005

and in a way that we wouldn't have expected.

173

00:06:18.005 --> 00:06:19.965

Obviously we're doing everything in a buildup approach.

174

00:06:20.385 --> 00:06:22.805

So, uh, we began with very low power on the aircraft,

175

00:06:22.805 --> 00:06:23.805

and you wouldn't have expected a lot

176  
00:06:23.805 --> 00:06:25.125  
of tail rotor for that configuration.

177  
00:06:27.025 --> 00:06:28.725  
Our flight controls team speculated, well,

178  
00:06:28.725 --> 00:06:29.925  
maybe we're not getting the tail rotor

179  
00:06:29.925 --> 00:06:31.165  
angles that we are asking for.

180  
00:06:32.025 --> 00:06:33.965  
Um, so, you know, obviously we,

181  
00:06:33.985 --> 00:06:36.805  
we get the tail rotor blade commands outta the flight

182  
00:06:36.805 --> 00:06:39.165  
controls, and we've sort of made the mistake of assuming

183  
00:06:39.195 --> 00:06:40.925  
that what the flight controls call is,

184  
00:06:40.925 --> 00:06:42.565  
my tail rotor blade angle is actually

185  
00:06:42.565 --> 00:06:43.605  
the tail rotor blade angle.

186  
00:06:44.105 --> 00:06:45.525  
Uh, the team jumped on the aircraft

187  
00:06:45.545 --> 00:06:46.845  
and measured the commanded

188  
00:06:46.845 --> 00:06:49.325  
and, uh, versus achieved angles with a digital protractor.

189  
00:06:49.785 --> 00:06:52.085

And we showed that we weren't getting the correct polarity

190

00:06:52.085 --> 00:06:53.725

of, uh, tailwater command

191

00:06:53.825 --> 00:06:55.685

or we weren't achieving what was being commanded.

192

00:06:56.225 --> 00:06:59.285

So, uh, there's a plot of, in green is what the mixing ought

193

00:06:59.285 --> 00:07:01.685

to have looked at, looked like versus collective position.

194

00:07:01.785 --> 00:07:03.005

Red was what we were actually getting.

195

00:07:03.705 --> 00:07:05.165

So obviously a problem there.

196

00:07:06.405 --> 00:07:07.445

I made the question, which one was

197

00:07:07.515 --> 00:07:08.685

left, which one was right.

198

00:07:10.665 --> 00:07:12.085

Uh, so where did the problem come from?

199

00:07:12.395 --> 00:07:15.165

Well, the, uh, the initial kinematics on the tail rotor

200

00:07:15.165 --> 00:07:18.045

and the simulator were based on 53 Echo, um, and,

201

00:07:18.045 --> 00:07:19.925

and other aircraft with a similar configuration.

202

00:07:20.465 --> 00:07:22.845

So that's a slight difference between Echo

203

00:07:22.845 --> 00:07:24.085  
and K that we'll see pretty soon.

204

00:07:24.225 --> 00:07:28.085  
Uh, during development, the rotors team updated the, uh, ICD

205

00:07:28.425 --> 00:07:29.565  
for the tail rotor,

206

00:07:29.785 --> 00:07:32.205  
but the, those, uh, that kinematic update wasn't then

207

00:07:32.205 --> 00:07:33.405  
reflected in the simulator.

208

00:07:33.785 --> 00:07:35.925  
So you're flying a simulator, uh, you know,

209

00:07:35.925 --> 00:07:37.605  
pilot input goes into a mixer.

210

00:07:37.875 --> 00:07:40.245  
That mixer makes a command in terms of, uh,

211

00:07:40.245 --> 00:07:41.605  
degrees over to the servos.

212

00:07:41.625 --> 00:07:44.725  
The kinematic in the sim turn that command in terms

213

00:07:44.725 --> 00:07:45.925  
of degrees into inches.

214

00:07:46.105 --> 00:07:47.485  
And then we have a model of the servos.

215

00:07:48.025 --> 00:07:50.085  
Uh, but then here's where fancy control

216

00:07:50.085 --> 00:07:51.165



system meets physics, right?

217

00:07:51.225 --> 00:07:53.525

So we have a model, the actuator position,

218

00:07:53.525 --> 00:07:55.045

and then we have a model of the swash plate,

219

00:07:55.045 --> 00:07:56.845

or in this case just the control rigging.

220

00:07:57.105 --> 00:07:59.765

And then that makes a tail rotor angle in the sim.

221

00:08:00.385 --> 00:08:02.005

So again, everything works fine in the sim.

222

00:08:02.005 --> 00:08:04.685

You can make these almost arbitrary, uh, mappings,

223

00:08:04.785 --> 00:08:06.965

and it'll work because you've modeled everything

224

00:08:06.965 --> 00:08:08.045

and you're just inverting the model.

225

00:08:08.585 --> 00:08:09.925

The moment you take that to an aircraft,

226

00:08:10.225 --> 00:08:11.405

uh, you can see problems.

227

00:08:11.665 --> 00:08:13.925

So here's a picture of the 53 echoes tail rotor,

228

00:08:14.065 --> 00:08:17.245

and here's a picture of the 53 Ks model of the tail rotor.

229

00:08:17.545 --> 00:08:19.085

Uh, you can see the pitch horns here.

230  
00:08:19.265 --> 00:08:20.565  
Uh, the pitch control rods here are

231  
00:08:20.565 --> 00:08:21.605  
on the leading edge of the blade here.

232  
00:08:21.605 --> 00:08:23.005  
They're on the trailing edge of the blade.

233  
00:08:23.425 --> 00:08:25.845  
So on identical servo command to the tail rotor

234  
00:08:25.845 --> 00:08:28.205  
between the two aircraft yields an opposite, uh,

235  
00:08:28.255 --> 00:08:29.445  
blade angle change.

236  
00:08:30.505 --> 00:08:33.085  
So that a fairly small modeling difference

237  
00:08:33.085 --> 00:08:35.805  
between the two obviously had, uh, pretty big results.

238  
00:08:38.065 --> 00:08:39.965  
So we do do a lot of work leading up to flight tests.

239  
00:08:39.965 --> 00:08:41.645  
We had a representative from NRC here this week.

240  
00:08:41.645 --> 00:08:43.245  
We also did a lot of testing on Rascal,

241  
00:08:43.265 --> 00:08:44.365  
but it's the same problem.

242  
00:08:44.785 --> 00:08:47.725  
So you put a model of your aircraft into their aircraft

243  
00:08:47.825 --> 00:08:48.925

and then invert that model

244

00:08:49.105 --> 00:08:52.485

and use their dynamics, uh, to pretend that you're a 53 K

245

00:08:52.485 --> 00:08:53.965

and not a Bell four 12 or an H 60.

246

00:08:54.385 --> 00:08:55.525

So again, that's not a place

247

00:08:55.525 --> 00:08:56.925

that you're going to find an error like this.

248

00:08:56.925 --> 00:08:58.605

You do a bunch of simulator testing, you do a bunch

249

00:08:58.605 --> 00:09:00.805

of surrogate aircraft testing, and nowhere do you have the

250

00:09:00.805 --> 00:09:02.085

opportunity to find this problem.

251

00:09:02.505 --> 00:09:05.005

So it's really, really comes down to us in flight tests to,

252

00:09:05.225 --> 00:09:07.285

you know, that once the error has made it to that point,

253

00:09:07.345 --> 00:09:09.005

it comes to us in flight tests to find it.

254

00:09:09.625 --> 00:09:13.485

So, uh, so there I was, uh, so I was out there on a,

255

00:09:13.485 --> 00:09:15.845

on a Saturday with my digital protractor measuring tail

256

00:09:15.935 --> 00:09:19.005

blade angles, and I had a had an opportunity to notice that,

257  
00:09:19.105 --> 00:09:21.365  
hey, when the guy in the cockpit's calling right pedal,

258  
00:09:21.385 --> 00:09:23.005  
the servo isn't moving in the right direction,

259  
00:09:23.065 --> 00:09:24.445  
and let's talk about why it didn't.

260  
00:09:25.545 --> 00:09:27.765  
Uh, so there's several reasons, uh, how it was missed.

261  
00:09:27.945 --> 00:09:29.565  
You know, obviously there's a lot of layers

262  
00:09:29.565 --> 00:09:30.645  
of Swiss cheese here happening,

263  
00:09:31.145 --> 00:09:34.125  
but in general, I ca I came down to five, uh,

264  
00:09:34.405 --> 00:09:35.445  
contributing factors that led

265  
00:09:35.445 --> 00:09:37.245  
to not catching this on the ground test vehicle.

266  
00:09:38.015 --> 00:09:39.325  
We'll go through each of those in detail.

267  
00:09:39.785 --> 00:09:41.365  
So the first one is the flight control system

268  
00:09:41.365 --> 00:09:42.405  
acceptance test procedure.

269  
00:09:42.505 --> 00:09:45.605  
We have ATPs for, you know, every system on the aircraft,

270  
00:09:45.605 --> 00:09:47.005

and they all get performed on each aircraft

271

00:09:47.025 --> 00:09:48.285

as it's delivered to flight test.

272

00:09:48.945 --> 00:09:52.005

So this F-C-S-A-T-P was done as part of the build,

273

00:09:52.345 --> 00:09:54.205

but it was done before the blades were installed.

274

00:09:54.545 --> 00:09:57.685

So the team who was doing the A TP was just looking at a

275

00:09:57.805 --> 00:09:59.725

servo and, you know, some rigging

276

00:09:59.745 --> 00:10:02.005

and didn't have the, the opportunity to look at the thing

277

00:10:02.005 --> 00:10:03.805

and see where the blade would go in response

278

00:10:03.805 --> 00:10:05.725

to the servo movement, unfortunately.

279

00:10:05.745 --> 00:10:07.485

So this, this did specifically check

280

00:10:07.485 --> 00:10:08.485

for the correct railroad

281

00:10:08.485 --> 00:10:10.125

or servo movement in response to pedal

282

00:10:10.125 --> 00:10:11.125

and collective inputs.

283

00:10:11.505 --> 00:10:13.765

The unfortunate thing is that the expected results from the

284

00:10:13.765 --> 00:10:15.205

A TP were based on the sim.

285

00:10:15.705 --> 00:10:17.365

So the sim that had the error in it is

286

00:10:17.365 --> 00:10:18.565

what generated the a TP

287

00:10:18.635 --> 00:10:20.325

that we followed when we installed the

288

00:10:20.325 --> 00:10:21.365

thing on, on the pedestal.

289

00:10:22.185 --> 00:10:24.045

Here's an, here's a picture of that, uh,

290

00:10:24.045 --> 00:10:25.245

tail rotor without blades.

291

00:10:25.545 --> 00:10:27.605

So again, you can imagine that all you're looking at is

292

00:10:27.685 --> 00:10:29.125

servo extender, server retract.

293

00:10:29.745 --> 00:10:31.565

You know, all of us have seen the design

294

00:10:31.565 --> 00:10:33.685

and knew which direction the blades were facing, uh,

295

00:10:33.685 --> 00:10:35.845

in the design, but without them in front of you is I think,

296

00:10:35.885 --> 00:10:37.525

a difficult thing for the team to, to check.

297

00:10:38.105 --> 00:10:41.045

So there I was, I wasn't actually there conducting the A TPI

298

00:10:41.045 --> 00:10:42.245

was conducting a follow on check

299

00:10:42.245 --> 00:10:43.445

of the tail rotor blade angles.

300

00:10:43.725 --> 00:10:45.565

I knew though that this a TP had been conducted.

301

00:10:45.905 --> 00:10:47.085

So I assumed, well,

302

00:10:47.275 --> 00:10:49.485

there's no major discovery to be had here.

303

00:10:49.545 --> 00:10:51.165

I'm just trying to check an angle on a blade,

304

00:10:51.505 --> 00:10:54.245

and I think limited the scope of my investigation

305

00:10:54.385 --> 00:10:56.165

and didn't allow, it didn't, uh, set me up

306

00:10:56.165 --> 00:10:57.885

to critically think about, you know,

307

00:10:57.885 --> 00:10:59.085

what, what there was to be learned.

308

00:11:01.665 --> 00:11:05.205

The next one up, we had a full check of the main rotor

309

00:11:05.205 --> 00:11:06.885

and tail rotor blade angles planned.

310

00:11:07.345 --> 00:11:08.845

But, uh, what we were out there, uh,

311  
00:11:08.845 --> 00:11:10.205  
that day conducting was really a,

312  
00:11:10.225 --> 00:11:11.965  
an abbreviated blade angle check.

313  
00:11:12.465 --> 00:11:13.925  
We had a big milestone coming up,

314  
00:11:13.925 --> 00:11:16.085  
which was the bladed light off of our ground test vehicle.

315  
00:11:16.625 --> 00:11:18.285  
And, uh, you know, big deal for the program,

316  
00:11:18.345 --> 00:11:19.525  
we put blades on a 53 K

317  
00:11:19.525 --> 00:11:20.925  
for the first time and, and spun it up.

318  
00:11:21.305 --> 00:11:23.965  
So, as you can imagine, there was some desire to get to that

319  
00:11:23.965 --> 00:11:26.325  
as quickly as possible and to minimize prerequisite tests.

320  
00:11:26.865 --> 00:11:29.525  
So we decided, well, this isn't really a prerequisite test

321  
00:11:29.525 --> 00:11:30.565  
to that bladed light off.

322  
00:11:30.575 --> 00:11:32.045  
We're, we're gonna stay at low pitch.

323  
00:11:32.255 --> 00:11:33.885  
We're not gonna put a lot of torque on the aircraft.

324  
00:11:33.885 --> 00:11:36.885



So if I have small differences in rigging between my, um,

325

00:11:36.885 --> 00:11:38.765

between my rotor blades, it shouldn't be a big deal.

326

00:11:38.765 --> 00:11:40.565

We get some vibrations, but let's not worry about that.

327

00:11:41.305 --> 00:11:42.645

So instead, we went out there

328

00:11:42.645 --> 00:11:44.245

and did a very initial, uh,

329

00:11:44.245 --> 00:11:46.045

blade angle check just to check the rig.

330

00:11:46.425 --> 00:11:47.485

You know, we had, uh,

331

00:11:47.585 --> 00:11:49.885

pre tracks on all the main rotor blades, uh,

332

00:11:49.885 --> 00:11:51.165

coming out of the whirl tower.

333

00:11:51.325 --> 00:11:53.610

I mentioned before that we can't whirl all seven rotor

334

00:11:53.610 --> 00:11:56.125

blades together, but we can whirl three of them together.

335

00:11:56.545 --> 00:11:58.285

So what they did was we had a, a master blade,

336

00:11:58.285 --> 00:12:00.645

and then we whirl two blades against the master

337

00:12:00.745 --> 00:12:03.085

and just iterate through the, the set that way.

338  
00:12:03.665 --> 00:12:06.325  
Um, one of our worries with was that this would allow errors

339  
00:12:06.325 --> 00:12:07.485  
to propagate in the rigging,

340  
00:12:07.545 --> 00:12:09.725  
and we would get dramatically differently raid

341  
00:12:09.915 --> 00:12:10.925  
main rotor blades.

342  
00:12:11.265 --> 00:12:13.805  
We were able to whirl the entire tail rotor together.

343  
00:12:13.825 --> 00:12:15.645  
So there was somewhat less focus on the tail

344  
00:12:15.645 --> 00:12:16.805  
rotor during this investigation.

345  
00:12:16.805 --> 00:12:19.085  
This was mostly on main rotor, uh, issue.

346  
00:12:19.525 --> 00:12:22.685  
I note here that I wasn't talking very effectively

347  
00:12:22.685 --> 00:12:23.845  
with the FTE and the cockpit.

348  
00:12:23.845 --> 00:12:25.285  
We were on radios and it was hard to hear him.

349  
00:12:25.585 --> 00:12:28.245  
So he was making pedal inputs, making collective inputs.

350  
00:12:28.325 --> 00:12:30.405  
I wasn't paying very much attention to what he was saying.

351  
00:12:30.705 --> 00:12:32.965

Uh, 'cause again, I was up there expecting measuring tail

352

00:12:32.965 --> 00:12:34.525

rotor blade angles, and that was it.

353

00:12:35.345 --> 00:12:38.445

Um, we also found, so remember the objective of this was

354

00:12:38.445 --> 00:12:41.605

to compare the rigging of each of the blades to one another.

355

00:12:42.085 --> 00:12:43.005

I measured two of the tail

356

00:12:43.005 --> 00:12:44.165

rotor blades, and they were identical.

357

00:12:44.165 --> 00:12:45.445

We measured the other two. They were identical.

358

00:12:45.865 --> 00:12:48.205

So from that perspective, I thought, oh, good, nothing

359

00:12:48.205 --> 00:12:49.445

to worry about on the tail rotor.

360

00:12:49.445 --> 00:12:51.285

This was after we had conducted all the checks on the main

361

00:12:51.285 --> 00:12:52.325

rotor and found some differences.

362

00:12:52.825 --> 00:12:55.205

Um, so that, again, degraded attention to detail and,

363

00:12:55.205 --> 00:12:58.645

and test, uh, because I wasn't expecting to be surprised.

364

00:12:59.085 --> 00:13:01.245

I was focusing on only one very narrow objective.

365

00:13:01.665 --> 00:13:03.485

And, uh, I was not attentive to discovery.

366

00:13:05.025 --> 00:13:08.005

So, uh, that, that's, that's a thing to keep in mind is

367

00:13:08.005 --> 00:13:11.405

that, you know, surprises are surprises, right?

368

00:13:11.405 --> 00:13:12.925

You can't, unless you're expecting

369

00:13:12.925 --> 00:13:14.205

to be surprised, you won't notice it.

370

00:13:14.865 --> 00:13:16.525

Uh, the other thing, this is probably new to a lot

371

00:13:16.525 --> 00:13:17.885

of people in flight test schedule pressure.

372

00:13:18.095 --> 00:13:20.085

Never heard of that, right? So, uh, I mentioned

373

00:13:20.085 --> 00:13:22.725

that we had delayed the, mentioned

374

00:13:22.725 --> 00:13:24.805

that we had delayed the blade angle check to the full thing

375

00:13:24.805 --> 00:13:25.805

to after the milestone.

376

00:13:26.225 --> 00:13:27.885

Um, we were conducting this initial check

377

00:13:27.885 --> 00:13:29.085

on second shift on a Saturday.

378

00:13:29.625 --> 00:13:31.285

Uh, so we had very few people there,

379

00:13:31.285 --> 00:13:32.885

and we didn't have extra sets of eyes with us.

380

00:13:32.885 --> 00:13:34.445

It was just the two of us, one on the cockpit,

381

00:13:34.445 --> 00:13:35.445

one back on the tail rotor.

382

00:13:35.785 --> 00:13:37.525

And as you can imagine, second shift on a Saturday,

383

00:13:37.585 --> 00:13:40.045

we didn't do a lot of rigorous data review after the fact.

384

00:13:40.105 --> 00:13:42.045

We did write down angles and,

385

00:13:42.145 --> 00:13:43.765

and in fact, in, in retrospect,

386

00:13:43.765 --> 00:13:46.165

the angles I had written down were sufficient, obviously,

387

00:13:46.165 --> 00:13:48.245

to prove to myself that the tail was backwards,

388

00:13:48.385 --> 00:13:51.085

but didn't look at them in enough detail, uh, in order

389

00:13:51.085 --> 00:13:52.165

to understand that real time.

390

00:13:52.705 --> 00:13:54.285

The next thing is, so why didn't I do it on Sunday?

391

00:13:54.285 --> 00:13:55.165

Well, Sunday we were doing

392

00:13:55.165 --> 00:13:56.565  
instrumentation safety and clearance checks.

393

00:13:56.825 --> 00:13:59.365  
So, uh, again, didn't spend the next day looking at data.

394

00:13:59.365 --> 00:14:01.325  
We instead spent it checking, uh, for,

395

00:14:01.505 --> 00:14:03.245  
for tight wires and for chafing.

396

00:14:03.625 --> 00:14:05.805  
Uh, we then spent the next, you know, we,

397

00:14:05.805 --> 00:14:07.685  
this is like a 13 day straight stretch of work.

398

00:14:07.825 --> 00:14:09.845  
So we spent the next week getting ready

399

00:14:09.845 --> 00:14:10.765  
for the bladed light off and

400

00:14:10.765 --> 00:14:11.765  
conducting the bladed light off.

401

00:14:11.765 --> 00:14:13.725  
So it wasn't until after that very first run

402

00:14:13.955 --> 00:14:15.085  
that we actually looked at the data

403

00:14:15.085 --> 00:14:16.245  
in any detail from this test.

404

00:14:17.025 --> 00:14:19.485  
Uh, again, that day on Saturday, we were under pressure

405

00:14:19.485 --> 00:14:20.725

to get off the aircraft and let maintenance

406

00:14:20.725 --> 00:14:22.285

and instrumentation continue putting it together.

407

00:14:23.025 --> 00:14:25.965

Um, however, even with the pressure, I had plenty of time

408

00:14:25.985 --> 00:14:28.045

to, to do this and understand what I was looking at

409

00:14:28.065 --> 00:14:30.485

and find the issue rather than, um,

410

00:14:31.075 --> 00:14:32.245

punting it for the next day.

411

00:14:32.745 --> 00:14:35.285

So this is one of those where even under time pressure,

412

00:14:35.285 --> 00:14:37.685

there's opportunity to, to learn things in flight test.

413

00:14:39.025 --> 00:14:40.285

The other thing, I mentioned this before,

414

00:14:40.385 --> 00:14:42.765

but we were very focused on the main rotor.

415

00:14:42.985 --> 00:14:44.285

Uh, because of the, the fact

416

00:14:44.285 --> 00:14:45.685

that we couldn't whirl the blades together,

417

00:14:46.465 --> 00:14:48.365

we did find some big pre track differences.

418

00:14:48.365 --> 00:14:49.965

So we spent quite a lot of time on that Saturday

419  
00:14:49.965 --> 00:14:52.045  
and Sunday talking about ELAs, hysteresis

420  
00:14:52.045 --> 00:14:53.245  
and elastomeric bearings,

421  
00:14:53.245 --> 00:14:55.885  
and why, why else might there be a difference in the rig

422  
00:14:55.885 --> 00:14:57.685  
between the blades when otherwise we wouldn't have expected

423  
00:14:57.685 --> 00:14:59.125  
very much coming out of the world tower.

424  
00:14:59.675 --> 00:15:01.325  
That ended up actually not being a problem.

425  
00:15:01.395 --> 00:15:03.445  
This was all correctly set on the world tower,

426  
00:15:03.445 --> 00:15:04.965  
and we didn't have a lot of, uh, track

427  
00:15:04.965 --> 00:15:06.285  
and balance changes to make initially.

428  
00:15:06.665 --> 00:15:07.885  
So the thing that we were measuring,

429  
00:15:07.885 --> 00:15:09.965  
that we were focusing on didn't really end up mattering.

430  
00:15:10.155 --> 00:15:12.685  
Like I said before, the tail angles were identical

431  
00:15:12.685 --> 00:15:15.405  
between all of the blades, so not a lot to be found there.

432  
00:15:16.185 --> 00:15:17.965



Uh, however, we focused on a red herring

433

00:15:18.185 --> 00:15:19.925

and, uh, again, a pretty classic mistake.

434

00:15:20.465 --> 00:15:22.845

The we had a, a real problem hiding right in front of us

435

00:15:22.845 --> 00:15:23.845

and instead focused on something that

436

00:15:23.845 --> 00:15:24.685

was completely irrelevant.

437

00:15:25.385 --> 00:15:27.685

Um, you know, Ben Lutheran, his paper, uh,

438

00:15:27.685 --> 00:15:29.805

yesterday talked about what time pressure does

439

00:15:29.805 --> 00:15:31.445

to people, and, uh, it said two things.

440

00:15:31.445 --> 00:15:33.285

He said that it decreases their performance

441

00:15:33.385 --> 00:15:36.165

and that you react by, uh, constraining your inputs.

442

00:15:36.225 --> 00:15:38.365

So this is one where, you know, in a,

443

00:15:38.365 --> 00:15:39.605

in a pressurized environment,

444

00:15:39.665 --> 00:15:41.245

we definitely constrained our inputs.

445

00:15:41.245 --> 00:15:43.005

And in instead of, uh, thinking about everything

446  
00:15:43.005 --> 00:15:44.965  
that was in front of us, we, we focus on one thing and,

447  
00:15:44.965 --> 00:15:46.165  
and lost everything else.

448  
00:15:47.825 --> 00:15:49.045  
The other, the last thing, uh,

449  
00:15:49.045 --> 00:15:51.965  
the last causal factor was a lack of expected results.

450  
00:15:52.305 --> 00:15:55.045  
So, you know, we have fairly complicated tail rotor blade

451  
00:15:55.045 --> 00:15:57.285  
geometry, and we were up there measuring on that, you know,

452  
00:15:57.315 --> 00:15:58.765  
very inboard cuff.

453  
00:15:59.425 --> 00:16:02.645  
Um, the guy in the cockpit was calling out FCC

454  
00:16:03.295 --> 00:16:04.565  
blade angle commands,

455  
00:16:04.565 --> 00:16:05.805  
but that actually didn't correlate

456  
00:16:05.805 --> 00:16:07.205  
to the number on the protractor.

457  
00:16:07.545 --> 00:16:10.645  
And the number on the protractor had sort of a, uh, uh,

458  
00:16:10.645 --> 00:16:12.285  
arbitrary sign convention depending on

459  
00:16:12.285 --> 00:16:13.365

where the tail rotor blade was.

460

00:16:13.365 --> 00:16:15.765

We have a canted tail rotor, so depending on where,

461

00:16:15.765 --> 00:16:17.605

where the blade is in terms of azimuth, that,

462

00:16:17.605 --> 00:16:18.685

uh, changes what the sign is.

463

00:16:18.685 --> 00:16:21.645

So it wasn't easy to hear a tail rotor blade angle command

464

00:16:22.025 --> 00:16:24.525

and, and translated into the number I was seeing

465

00:16:24.545 --> 00:16:25.765

on the inclinometer.

466

00:16:26.345 --> 00:16:28.285

Um, mentioned the complicated geometry.

467

00:16:28.785 --> 00:16:29.965

And, uh, we didn't have it with us.

468

00:16:30.065 --> 00:16:31.965

So we, we could have had prior to it.

469

00:16:32.065 --> 00:16:34.325

Here's the number I will see on the protractor if

470

00:16:34.325 --> 00:16:35.485

everything is matching correctly.

471

00:16:35.665 --> 00:16:37.045

Didn't bother with that. We just went out there

472

00:16:37.045 --> 00:16:38.485

and measured it and then took the measurements home.

473  
00:16:38.985 --> 00:16:41.645  
Um, so again, expect results would've been in a great way

474  
00:16:41.645 --> 00:16:43.925  
to, uh, to found this issue while

475  
00:16:43.925 --> 00:16:45.045  
we were conducting the test.

476  
00:16:45.545 --> 00:16:48.205  
So how do we recover? Uh, pretty major issue.

477  
00:16:48.205 --> 00:16:50.485  
We talked a lot about this this week about how we need many,

478  
00:16:50.485 --> 00:16:52.085  
many software drops in order to get

479  
00:16:52.085 --> 00:16:53.285  
through a developmental test program.

480  
00:16:54.105 --> 00:16:56.645  
Uh, well, so the structural loads engineers

481  
00:16:56.645 --> 00:16:57.685  
were the ones who pointed us to this.

482  
00:16:57.685 --> 00:16:59.605  
Again, they, they had a independent data source,

483  
00:16:59.605 --> 00:17:02.405  
which is their, uh, tail rotor, uh, blade strains

484  
00:17:02.405 --> 00:17:04.365  
and the compressive load on the support strut.

485  
00:17:04.705 --> 00:17:05.965  
So that was what called it out.

486  
00:17:05.965 --> 00:17:07.765

And then some critical thinking from others on the flight

487

00:17:07.765 --> 00:17:09.885

controls team, uh, pointed us in this direction.

488

00:17:10.425 --> 00:17:13.085

So the design team, uh, in concert with the test team,

489

00:17:13.085 --> 00:17:14.925

conducted a end-to-end review of the control system.

490

00:17:14.925 --> 00:17:16.845

We were looking for any other errors like this

491

00:17:16.845 --> 00:17:19.085

that could have made their way through, um,

492

00:17:19.315 --> 00:17:21.125

that was conducted fairly successfully.

493

00:17:21.145 --> 00:17:22.365

We didn't find any other problems.

494

00:17:23.065 --> 00:17:24.805

And the results were, uh, submitted

495

00:17:24.805 --> 00:17:26.125

to the model design safety committee

496

00:17:26.125 --> 00:17:27.765

that we talked a bit about a couple of days ago.

497

00:17:28.105 --> 00:17:30.525

Uh, Dave Walsh, who I think was here at least yesterday,

498

00:17:30.595 --> 00:17:33.605

chaired the, uh, investigatory board into this issue.

499

00:17:33.605 --> 00:17:35.805

So we had a lot of senior help on, uh, trying

500  
00:17:35.805 --> 00:17:37.165  
to make sure we didn't have any other problems,

501  
00:17:37.185 --> 00:17:39.245  
and then investigating how we made this error.

502  
00:17:40.785 --> 00:17:43.205  
Uh, we then conducted what we had planned to do all along,

503  
00:17:43.205 --> 00:17:45.685  
which was the full main rotor, uh, cube check,

504  
00:17:45.685 --> 00:17:48.925  
measuring blade angles across the control envelope in order

505  
00:17:48.925 --> 00:17:50.165  
to look for, again, other problems.

506  
00:17:50.165 --> 00:17:52.165  
And we compare the measured results to what we achieved.

507  
00:17:52.185 --> 00:17:53.285  
And except for the tailer,

508  
00:17:53.285 --> 00:17:54.565  
like I said, everything went, went well.

509  
00:17:55.345 --> 00:17:57.845  
Um, then we use these flight test variables.

510  
00:17:57.845 --> 00:17:59.965  
So I know a lot of, uh, the advanced programs have these,

511  
00:17:59.985 --> 00:18:03.245  
but we have a, a wide variety of flight test adjustable, uh,

512  
00:18:03.245 --> 00:18:05.605  
parameters that we can add into the controls

513  
00:18:05.605 --> 00:18:06.765

without a software drop.

514

00:18:07.145 --> 00:18:08.325

So the designers were able

515

00:18:08.325 --> 00:18:10.285

to invert the entire tail mixing matrix

516

00:18:10.545 --> 00:18:13.925

and correct the sign error, uh, using just FTDs.

517

00:18:13.925 --> 00:18:15.485

We actually did not need a software

518

00:18:15.485 --> 00:18:16.725

drop in order to fix this problem.

519

00:18:16.855 --> 00:18:18.805

Eventually we did, but not during ground test.

520

00:18:20.185 --> 00:18:22.485

So we resumed normal testing in nine business days.

521

00:18:22.905 --> 00:18:24.005

Uh, pretty major error.

522

00:18:24.065 --> 00:18:27.645

We did a, an extensive review of the entire system design

523

00:18:28.105 --> 00:18:30.285

and less than two weeks later we were back into test.

524

00:18:30.745 --> 00:18:33.565

So a pretty big win, I think on the recovery side of this,

525

00:18:33.715 --> 00:18:36.405

that, you know, Hey, let's, let's stop, let's think about

526

00:18:36.405 --> 00:18:39.285

what the problems are and where we're at in terms of safety.

527

00:18:39.585 --> 00:18:41.125

And then once you prove you're safe, let's get back to work.

528

00:18:41.345 --> 00:18:44.245

You know, uh, so quite, quite useful, uh, use

529

00:18:44.245 --> 00:18:46.965

of flight test variables that,

530

00:18:46.965 --> 00:18:48.205

that got us through ground test.

531

00:18:48.265 --> 00:18:51.645

So we, um, we did all of our planned, uh,

532

00:18:51.645 --> 00:18:53.645

ground test vehicle testing with that, uh,

533

00:18:53.645 --> 00:18:54.685

flight test variable set

534

00:18:54.695 --> 00:18:56.765

until we got our final first flight software bill

535

00:18:56.765 --> 00:18:57.605

and then put that on, which

536

00:18:57.605 --> 00:18:58.885

obviously had the correct mixing in it.

537

00:18:59.385 --> 00:19:00.765

Uh, we've flown quite a bit since then.

538

00:19:00.765 --> 00:19:03.765

So first flight was on, uh, October 27th of last year,

539

00:19:04.035 --> 00:19:05.205

just about six months ago.

540

00:19:05.825 --> 00:19:08.645



Our, uh, second test aircraft, EDM three flew in January,

541

00:19:09.345 --> 00:19:11.245

and since then we've had 45 flights.

542

00:19:11.425 --> 00:19:12.925

So, uh, we'll see if they fly in today,

543

00:19:12.945 --> 00:19:14.085

but, uh, doing quite well.

544

00:19:14.085 --> 00:19:17.125

So 45 flights in, in six months on two aircraft is, uh,

545

00:19:17.125 --> 00:19:18.565

I think pretty good progress for a developmental

546

00:19:18.565 --> 00:19:19.685

program on a new design.

547

00:19:20.685 --> 00:19:21.845

I mentioned the ground test.

548

00:19:21.845 --> 00:19:23.725

So we've, we've been conducting hundreds of hours

549

00:19:23.745 --> 00:19:25.005

of ground test over about two

550

00:19:25.005 --> 00:19:26.445

and a half years on the ground test vehicle,

551

00:19:27.065 --> 00:19:28.845

and we've been continuing envelope expansion.

552

00:19:28.905 --> 00:19:30.845

So we, um, a couple of weeks ago picked up our

553

00:19:30.845 --> 00:19:32.005

12,000 pound external load.

554

00:19:32.045 --> 00:19:33.565

A couple of press releases came out about that.

555

00:19:34.025 --> 00:19:36.085

And as it's the primary mission of this helicopter,

556

00:19:36.085 --> 00:19:37.485

quite a bit of our envelope expansion

557

00:19:38.135 --> 00:19:41.085

scope is gonna be dedicated to external envelope expansion

558

00:19:41.085 --> 00:19:43.525

and development, or I mentioned a DS 33.

559

00:19:43.525 --> 00:19:44.765

So all those standards apply

560

00:19:44.765 --> 00:19:46.965

to externally loaded configurations as well as internal.

561

00:19:46.985 --> 00:19:48.685

So there's a lot of maneuvering left to do for us.

562

00:19:50.025 --> 00:19:53.205

Uh, so in conclusion, we test for a reason and,

563

00:19:53.265 --> 00:19:55.125

and there are surprises out there to be had.

564

00:19:55.645 --> 00:19:57.045

I think sometimes it's tempting to think

565

00:19:57.045 --> 00:19:58.645

that we're just verifying a design

566

00:19:58.745 --> 00:20:01.045

or that there are only very minor, uh,

567

00:20:01.045 --> 00:20:03.525

developmental discoveries to be had during flight tests.

568

00:20:03.585 --> 00:20:05.405

But these are prototype vehicles

569

00:20:05.585 --> 00:20:08.245

and, uh, anything you can imagine is out there.

570

00:20:09.705 --> 00:20:11.405

The other thing is you make it a mistake early

571

00:20:11.585 --> 00:20:13.205

and it's very easy for that mistake to,

572

00:20:13.465 --> 00:20:15.925

to work its way into all of your documentation.

573

00:20:16.025 --> 00:20:20.725

So that one ICD miss years ago ended up in the simulator.

574

00:20:20.725 --> 00:20:21.965

It ended up in our surrogate aircraft.

575

00:20:21.985 --> 00:20:24.805

It ended up in the documentation that we used initially

576

00:20:24.805 --> 00:20:27.405

to check out this very characteristic on the aircraft.

577

00:20:27.905 --> 00:20:29.405

So, uh, question everything.

578

00:20:29.545 --> 00:20:31.765

And really the, the way to have avoided this would've been

579

00:20:31.765 --> 00:20:33.925

for someone standing there looking at the tail rotor blade

580

00:20:33.985 --> 00:20:35.885

to say, Hey, he stepped on the right pedal.

581  
00:20:36.105 --> 00:20:38.685  
Did that railroad blade move in the right direction

582  
00:20:38.685 --> 00:20:39.765  
for me to ya to the right?

583  
00:20:40.305 --> 00:20:42.445  
And that is something that is un incontrovertible.

584  
00:20:42.445 --> 00:20:45.085  
That's where physics takes control over wires.

585  
00:20:46.665 --> 00:20:48.805  
Uh, fly by wire is powerful for good and bad.

586  
00:20:48.865 --> 00:20:51.485  
So we can make that sign error, but then we can also fix it.

587  
00:20:51.825 --> 00:20:54.085  
So that's a quick way to recover from a problem is

588  
00:20:54.085 --> 00:20:55.885  
to use our fly by wire features again, to,

589  
00:20:55.905 --> 00:20:58.005  
to get back on track even after there's been a problem.

590  
00:20:59.745 --> 00:21:01.325  
And, uh, the ground test vehicle is worth the cost.

591  
00:21:01.325 --> 00:21:03.805  
So you can imagine that buying an entire 53 K just

592  
00:21:03.805 --> 00:21:05.445  
for ground test was, uh,

593  
00:21:05.605 --> 00:21:07.125  
an expensive commitment by the program.

594  
00:21:07.425 --> 00:21:09.085

But here's an, here's a case where we

595

00:21:09.845 --> 00:21:11.365

absolutely safe schedule because of it.

596

00:21:11.465 --> 00:21:14.925

So, I mean, forget about, we wouldn't have been unsafe.

597

00:21:14.985 --> 00:21:17.125

You know, you go out there for the very first taxi event

598

00:21:17.125 --> 00:21:18.925

and you try to make a taxi turn and you go the other way.

599

00:21:19.265 --> 00:21:20.445

It would've been apparent that it was

600

00:21:20.445 --> 00:21:21.685

wrong then before we flew.

601

00:21:21.945 --> 00:21:24.285

But the ground test vehicle, you don't wanna discover

602

00:21:24.285 --> 00:21:25.805

that the day before first flight, right?

603

00:21:25.905 --> 00:21:28.045

So, uh, from a programmatic cost

604

00:21:28.045 --> 00:21:29.525

and schedule perspective, I think that,

605

00:21:29.525 --> 00:21:31.045

that this thing was worth its weight in gold.

606

00:21:31.355 --> 00:21:33.485

This isn't actually the GTV, it's an EDM.

607

00:21:34.025 --> 00:21:35.485

Uh, and actually that's all I've got.

608  
00:21:35.545 --> 00:21:36.725  
So does anyone have questions?

609  
00:21:41.955 --> 00:21:42.955  
Thank you.

610  
00:21:51.475 --> 00:21:53.445  
Just a second. Wait the mic up here.

611  
00:21:54.225 --> 00:21:58.845  
Um, Okay, here we go.

612  
00:21:59.275 --> 00:22:01.885  
Done. So Claude, we gonna fix that.

613  
00:22:02.225 --> 00:22:05.285  
Um, basically what

614  
00:22:05.285 --> 00:22:08.005  
You pointed out to is something we all run into, which is,

615  
00:22:08.065 --> 00:22:11.605  
uh, uh, sculpt, uh, scheduled pressure.

616  
00:22:12.345 --> 00:22:16.085  
And you, your example was very, very, very relevant

617  
00:22:16.085 --> 00:22:17.205  
because we all see it.

618  
00:22:17.965 --> 00:22:19.605  
Saturdays minimum team,

619  
00:22:20.585 --> 00:22:23.165  
people got wanna see their families and wanna do stuff.

620  
00:22:23.165 --> 00:22:24.805  
You're in a hurry, you're trying to get stuff done.

621  
00:22:24.805 --> 00:22:26.885

You gotta make that barbecue to get home at night.

622

00:22:27.125 --> 00:22:30.765

I know how things go. Yep. And, and so you, you miss stuff.

623

00:22:30.865 --> 00:22:34.625

And it's not by not on

624

00:22:34.625 --> 00:22:36.185

purpose, it's not by intent.

625

00:22:36.185 --> 00:22:38.545

It's just the reality of flight tests sometimes.

626

00:22:39.685 --> 00:22:41.505

And, and you have expected results

627

00:22:42.045 --> 00:22:44.545

and you're looking to, it's where you expect,

628

00:22:44.965 --> 00:22:47.945

and again, without good models

629

00:22:48.125 --> 00:22:51.545

or without good predictions in, in your, in your quiver,

630

00:22:51.545 --> 00:22:54.185

if you would, uh, it makes it very difficult to,

631

00:22:54.185 --> 00:22:55.345

to see those miscon compares.

632

00:22:55.425 --> 00:22:56.665

'cause you see everything's looking the same.

633

00:22:56.765 --> 00:22:58.145

So it must be good. Okay.

634

00:22:58.645 --> 00:23:02.145

So I think this is a very relevant, uh, presentation.

635

00:23:02.145 --> 00:23:04.425

Thank you for your frankness on this objection. Sure.

636

00:23:06.135 --> 00:23:07.135

Alright, Thank you.

637

00:23:17.745 --> 00:23:20.305

I, I certainly second, uh, Jerry's remarks there,

638

00:23:20.365 --> 00:23:22.185

really excellent presentation, uh,

639

00:23:22.185 --> 00:23:23.465

completely different than the one

640

00:23:23.465 --> 00:23:25.665

before it, you know, F 35, air on fire,

641

00:23:25.675 --> 00:23:27.825

white scarf, all that kind of stuff.

642

00:23:28.045 --> 00:23:31.585

Uh, and then the 197 knot, uh, CH 53 K,

643

00:23:31.585 --> 00:23:33.305

which is a remarkable vehicle in its own right.

644

00:23:33.305 --> 00:23:34.305

So, but totally different.

645

00:23:34.405 --> 00:23:36.905

Uh, that's the beauty of, uh, these kinds of symposiums

646

00:23:36.905 --> 00:23:38.425

to have, uh, uh,

647

00:23:38.425 --> 00:23:40.665

technical discussions about all kinds of different products.

648

00:23:40.925 --> 00:23:44.185



Um, in that presentation, I found it interesting that, uh,

649

00:23:44.335 --> 00:23:46.925

much like, uh, many of the military's predecessors

650

00:23:46.925 --> 00:23:51.605

with new airplanes, E 2D, uh, F 18 EFG, et cetera,

651

00:23:51.945 --> 00:23:55.605

um, and others, uh, I think it's a sign of the times that,

652

00:23:55.605 --> 00:23:58.045

uh, aircraft may be named the same as one

653

00:23:58.045 --> 00:23:59.445

of their predecessors, but they're largely

654

00:23:59.445 --> 00:24:00.725

completely new aircraft.

655

00:24:01.265 --> 00:24:02.965

Um, it's a sign of the times.